TECH BRIEF 72

MAXIframe® 202 BRACKET

The Rondo MAXIframe® 202 Sill/Header Bracket has been modified to ensure there is no overhang of the section that could interfere with the linings, whilst still maintaining security of the MAXIjamb® Sill/Header section during installation. >>

RONDO®

www.rondo.com.au

MAXIframe® 202 BRACKET

The new 202 bracket design means one fixing flange is visible and the other invisible.

Once the bracket is installed against the web of the MAXIjamb® using 4/#10 wafer head tek screws, the MAXIjamb® section has to be 'rolled' into place as illustrated *(figures 1–3).*



FIGURE 1

FIGURE 2



FIGURE 3

The exposed flange has two pre-drilled holes for fixing to the MAXIjamb®, whilst the flange that is now inside the MAXIjamb® should be secured by fixing the screws through the top, 25mm in from the inside jamb face and 25mm from the outer edge of the section *(figure 4).*



FIGURE 4

This new bracket is fixed to the MAXIjamb® with the shorter internal flange facing the opening.

For example: when securing the sill member the short flange faces up and when securing the header, it faces down. *(For your convenience, the Rondo 202 Sill/Header Bracket is stamped accordingly on its inner face.)*

Once finally secured into place, the outer face of the 202 Sill/Header Bracket will align neatly with the face of the MAXIjamb® section, both internally and externally.

RONDO®

© 2013 Rondo Building Services Pty Ltd. ABN 69 000 289 207.
All Rights Reserved